



圖 害 震 橋

度
呪拾貳爲

SIDE AND FR OF KISOGAWA

Showing the condition after the earth
All piers and abutments cracked at a few feet ab
less displaced in var
Scale : 20 ft. to



木曾川

尺
寸
以
ON THE VIEW

BRIDGE.

quake disaster of Oct. 28th, 1891.

ove the top of foundation wells and more or
ious directions.

an inch.

