

圖脚橋造改橋川良長

ELEVATION AND PLAN

OF

NAGARAGAWA BRIDGE PIERS.

As reconstructed after the earthquake disaster of Oct. 28th, 1891, by using elliptical foundation brick well and building in several keystone at the portion near the ground surface and the structure built up as shown, with object to increase the sectional area of the pier near the river bed, which has been proved to be most likely attacked portion by earthquake.

SIDE VIEW

FOR

PIERS Nos. 4, 5, 6, 7 & 8.

