

長良川橋震害略圖

度 尺
呎拾貳為吋壹以

ELEVATION AND PLAN



OF

NAGARAGAWA BRIDGE.


Showing the condition after the earthquake disaster of Oct. 28th, 1891.

All piers broken and two piers No. 3 and No. 4 entirely failing. The girders fall down as shown.

Scale: 20 ft. to an inch.



側 面



平 面

