


# ニノ町コベルトル震害圖

## NINOMACHI CULVERT.


(258<sup>M</sup>. 45<sup>CH</sup>. 34)

Showing the condition after the great earthquake disaster of Oct. 28th, 1891.  
The embankment and the culvert cracked through as shown.

Scale : 4 ft. to an inch.



CROSS SECTION.



LONGITUDINAL SECTION.